


FIG. 1



—▲— CONDITION(2)
--*-- CONDITION(3)

FIG. 2

FIG. 3




FIG. 4




FIG.5A


 $Y = 0.00$ 

FIG.5B


 $Y = 0.02$
($W = 1.30$)

FIG.5C


 $Y = 0.05$
($W = 2.70$)

FIG.5D


 $Y = 0.07$
($W = 4.00$)

FIG.6A

$Y = 0.00$




FIG.6B

$Y = 0.02$
($W = 1.30$)




FIG.6C

$Y = 0.05$
($W = 2.70$)




FIG.6D

$Y = 0.07$
($W = 4.00$)





FIG. 7

FIG. 8




FIG. 9




FIG.10A

$Y = 0.00$




FIG.10B

$Y = 0.15$
($W = 8.50$)




FIG.10C

$Y = 0.29$
($W = 17.00$)




FIG.10D

$Y = 0.43$
($W = 25.50$)




FIG.11A


 $Y = 0.00$ 

FIG.11B


 $Y = 0.15$
($W = 8.50$)

FIG.11C


 $Y = 0.29$
($W = 17.00$)

FIG.11D



 $Y = 0.43$
($W = 25.50$)

FIG.12




FIG.13




FIG.14

FIG.15




FIG.16




FIG.17A


 $Y = 0.00$ 

FIG.17B


 $Y = 0.02$
($W = 1.30$)

FIG.17C


 $Y = 0.05$
($W = 2.70$)

FIG.17D


 $Y = 0.07$
($W = 4.00$)

FIG.18A


 $\gamma = 0.00$ 

FIG.18B


 $\gamma = 0.02$
($W = 1.30$)

FIG.18C


 $\gamma = 0.05$
($W = 2.70$)

FIG.18D



 $\gamma = 0.07$
($W = 4.00$)

FIG.19

FIG.20







FIG.21




Y= 0.00
FIG.22A



Y= 0.14
(W= 7.90)
FIG.22B



Y= 0.27
(W=15.70)
FIG.22C



Y= 0.40
(W=23.60)
FIG.22D




FIG.23A


 $Y = 0.00$ 

FIG.23B


 $Y = 0.14$
($W = 7.90$)

FIG.23C


 $Y = 0.27$
($W = 15.70$)

FIG.23D



 $Y = 0.40$
($W = 23.60$)

FIG.24




FIG.25




FIG.26




FIG.27

FIG.28




FIG.29




FIG.30A

$Y = 0.00$




FIG.30B

$Y = 0.05$
($W = 3.10$)




FIG.30C

$Y = 0.11$
($W = 6.10$)




FIG.30D

$Y = 0.16$
($W = 9.20$)




FIG.31A

Y= 0.00




FIG.31B

Y= 0.05
(W= 3.10)




FIG.31C

Y= 0.11
(W= 6.10)




FIG.31D

Y= 0.16
(W= 9.20)





FIG.32




FIG.33




FIG.34




FIG.35

FIG.36




FIG.37




FIG.38A

Y= 0.00




FIG.38B

Y= 0.05
(W= 2.90)




FIG.38C

Y= 0.10
(W= 5.80)




FIG.38D

Y= 0.15
(W= 8.60)




FIG.39A


 $Y = 0.00$ 

FIG.39B


 $Y = 0.05$
($W = 2.90$)

FIG.39C


 $Y = 0.10$
($W = 5.80$)

FIG.39D



 $Y = 0.15$
($W = 8.60$)

FIG.40




FIG.41




FIG.42




FIG.43

FIG.44




FIG.45




FIG.46A

Y= 0.00




FIG.46B


Y= 0.05
(W= 2.90)

FIG.46C


Y= 0.10
(W= 5.80)

FIG.46D


Y= 0.15
(W= 8.60)

FIG.47A

$Y = 0.00$




FIG.47B

$Y = 0.05$
($W = 2.90$)




FIG.47C

$Y = 0.10$
($W = 5.80$)




FIG.47D

$Y = 0.15$
($W = 8.60$)





FIG.48




FIG.49